

Subject: Starter Ring Gear

Affected engine models: Engine model
L 2400 EB 1.AD

Background information: Change of material for ring gear.

Priority: Immediate

Compliance: The previous ring gear is exchanged by a ring gear manufactured out of a magnesium alloy.
Engines in operation will be retrofitted during the next factory repair or overhaul.

Remarks: This document has been translated to the best of our knowledge. In case of doubt however only the German original shall be considered authoritative.

LBA approved:



15. Nov. 1993

Bearb.: Stolinski

Replaces Edition from: 03.09.91

Page: 1

Gepr.:



Edition: 01.12.92

of 1 Pages