

Subject: Piston Pin

Affected engine models: All engine models

L 2400 ET, L 2400 DT

Background information: A single case of engine damage with a broken piston pin. An investigation did not reveal conclusive results regarding the cause for the failure.

Priority: before next annual check

Compliance: A check of the material strength of the piston pin showed adequate values as shown during certification. To prevent such failures, all engines of the abovementioned type shall be equipped with reinforced piston pins.
Part number of the previous piston pin: 250.041.010.000
Part number of the new piston pin: 250.041.011.000

Approval: The technical content of this Technical Bulletin is approved by the LBA.

Note: This document has been translated to the best of our knowledge. In case of doubt however only the German original shall be considered authoritative.