

**Subject:** Sealing compound CURIL-T, Part Number: 170.211.200.000

**Affected engine models:** All engine models:

**L 1700**

**L 2000**

**L 2400**

**Background information:** Leaks on joints or threads that are sealed with CURIL-T, P/N: 170.211.200.000.

**Priority:** On occurrence of leaks, repairs, overhaul and manufacture of affected parts

**Compliance:** The sealing compound CURIL-T, P/N: 170.211.200.000 is replaced with ELASTOSIL N 189 sealing compound P/N: 708.413.004.000 in locations where previously CURIL-T was specified. Parts must be cleaned, dry, dust- and grease-free when assembled.

**Note:** This document has been translated to the best of our knowledge. In case of doubt however only the German original shall be considered authoritative.

**Approval:** This Technical Bulletin is approved in accordance with the procedures of the LBA approved development organisation LBA.NSD.006.