

TB-No.	Subject	L 1700	L 2000	L 2400
5	Alternator Ducati - Ducellier	EA only		
8.2	Float Needle Valve	all	all	EB, EE only
9.12	Extension of TBO	all	all	all
11.4	Ground Contact	all	all	all
12	Carburetor (porous and cracky diaphragm)	all		
13.5	Cylinderhead (worn valve seatings)	all	all	all
14	Crankcase (cracks due to propeller inst.)	EA only		
15	Magneto Slick (cracked ignition coil)	all	all	
17	Engine Designation Change	all	all	all
18	Magneto (increase lubrication cup)	except EA	except EA	
20.3	Magneto Slick (250 h inspection)	all	all	EB, EE only
23	New Bosch Alternators	except EA	except EA	
25	Accessory Case	except EA	except EA	
26.3	Cylinderhead Stud Bolts (new - old)	all	except DA	
27	Dip Stick Oil Level Markings	all	all	all
28	Engine Overheat (corrective measures)	all	all	all
29	Replacement Engine Installation G 109 A		EB1.AA only	
30	New Crankshaft Hardening Procedure		all	all
31.1	Accessory Case Mounting Bolts		DA only	
32	Engine Mount Bolts	except EA	except EA	all
34.1	Starter Gear Ring			EB1.AD only
37	Engine Type Designation - Stemme S 10			TPF only
39.1	New Starter		EA only	
42.1	Cylinderhead Modifications	all	all	
44.1	Too High Engine Temperatures	all	all	all
45	Carburettor - new metering needle		except EB	
47	Sticking intake valves			EB1.AD only
48	Engine oils	all	all	all
49	Push rods	all	all	all
50	Fuel hoses	all	all	all
51	Spark Plug Bosch WB4A	all	except DA	EB, EE only
52	Starter shaft support for starter SJCE 0,9 kW		only EA	
54	Oil- and Fuel hose assemblys	all	all	all
55	Float in carburetor Stromberg Zenith 150 CD and 150 CD 3	all	all	EB, EE only
57.1	Starter Magneton 1 kW	all	all	all
58	Cylinder	all		
59	Flame retardant protection sleeves for oil and fuel hoses	all	all	all
60	Ignition system			EF only
61	Intake Manifold	EB only	EB only	EB only
62	Electronic Control Unit ECU			EF, DF, ET, DT only
63.4	Spark Plug Limbach LB-L41.0 and LB-N41.0	all	all	EB, EE only
64	Sealing compound CURIL-T	all	all	all
65	Piston and Cylinder Head	all	EA only	
66	Piston Pin			ET, DT only

TB-No.	Subject	L 1700	L 2000	L 2400
67.1	Throttle lever spring			except EB, EE
68.1	New crankshaft		all	all
69	Spacer			except EB, EE
70	New turbocharger			only ET, DT
71	Fuels	all	all	all
72	Fuel pump	all	all	

Any Technical Bulletin not listed has been rejected or has become ineffective by type certificate data sheet amendment.